**Please Note:** The Wayne County system of GPS Monuments was established in January of 2000. The table below lists various notifications of GPS monuments that have been reported to be disturbed, missing, damaged, positioning error, described incorrectly, etc.

If you would like to make a report of any problem you might have encountered with an existing GPS monument, please notify the Wayne County Engineer's Office at the following phone number: **330-287-5500**.

| GPS Monument | Date Reported | Reported by | Remarks |
|---|---|---|---|
| PAI-6 | 3-17-05 | Brent Winslow, P.S. | Monument is correct. Latitude (N) should be 40º**43'** 13.07709" |
| WAY-2 | June 2005 | Wayne County Engineer's Office | Monument is located west of Geyers Chapel Road not Honeytown Road. (See Station References) |
| CHI-3 | 9-29-06 | Lynn Snyder, P.E., P.S. | Possible positioning error. |
| CHI-3 | 10-2-06 | Joseph Moine, Jr., P.S. | Possible positioning error. |
| PLA-3 | 10-2-06 | Plain Township | Hit monument with mower. May have disturbed it. |
| G281 | 11-16-09 | Wayne County Highway Department | Culvert and headwall/monument removed (42" CMP installed). Monument to be reset. |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |